

JHW-181



FEATURES

1.5v Operate

Dual - Channel (IN/OUT) Temperature Measurement

Low Standby Current (typ. 2uA)

Operating Current (typ. 25uA)

Measuring Temperature Range : Indoor -20 ~ +70 degC

Outdoor -50 ~ +70 degC

Display Resolution : 0.1 degC

Accuracy : +/- 1 degC

degC /degF Switchable

MAX/MIN Temperature records

FREEZE - ALERT

Key- Tone

Temperature alert :

Ice alert range -1 degC to +4 degC.

OPERATIONS

Press C/F : Toggle for DegC and DegF

Press Alert : Toggle for Freeze Alert On and Off

Alert On : Buzzer on 5 seconds and off 55 seconds
when the Outdoor Temp between -1degC
and +4degC.

Press Max/Min : Display the recorded Max or Min Temperature

Holding Max/Min for 1 Second : Clear the Max and Min

Temperature to current Temp.

